

- Airport
- Seaport
- Main roads (OSM)
- Primary
- Secondary
- Schools
- Settlements
- Capital city
- town
- village
- Admin Areas

Chateaubelair Primary School

The section housing the principal office forming the shorter stroke of the F is damaged. There was minor damage to the roof of the school, but the affected area has since been repaired by BRAGSA. Existing leakage in the computer lab roof was exacerbated by the hurricane. One sheet of galvanize partially dislodged. Leakage in one of the classrooms.

Owia Government School

Damage to the roof of the north-eastern side of the building that houses mainly the Early Childhood Centre. Half of the roof dislodged. Substantial damage to the preschool wing of the school. The entire roof would have to be replaced, including casting a ring beam to facilitate the rafters. Damage to the front fence. Ceiling of Grade 1 & 2 classroom in the Early Childhood Centre compromised.

Buccament Government School

There is minor damage to the ceiling in both the staff room and the toilet. The damage, while not currently posing an immediate safety risk, may become more problematic over time, potentially leading to the need for more significant repairs if not dealt with promptly. The window in the watchman's booth was dislodged. This situation is a security concern in respect of the safety and security of the school's staff and premises.

North Union Secondary School

Minimal damage to the facility. The full functioning of galvanize need to be replaced.

Troumaca Ontario Secondary School

Sections of the building received extensive damages and must be repaired to facilitate continuity of learning at this institution.

Adelphi Secondary School

Two buildings have suffered roof damage. Building 1 roof – IT lab, Library, 2 Form 1 Classrooms). Building 2 roof – Kitchen, Science Lab. Roof in Home Economics Laboratory, Library, Science Laboratories, 2 Form 1 Classroom has been compromised.

Barrouallie Government School

Several sheets of galvanize partially dislodged on the section that houses the library.

Questelles Government School

The roof is compromised with signs of not being partially securely attached to the building. Damage to guttering.

Emmanuel High School Mesopotamia

Twenty (20) sheets of galvanize were dislodged from the roof. Ceiling compromised and collapsed in one classroom.

Clare Valley Government School

Minor damage to the roof. Part of the ceiling in the principal's office collapsed.

Campden Park Secondary School

The electrical has been compromised and must be shut down. The floors are flooded with water, despite continuous cleaning efforts. Tiles on the floor are loose and portions of the roofing materials ceiling are caving in. There is evidence of extensive damage to the roof of one of the original buildings.

St. Joseph Convent Mesopotamia

Damage roof needs to be urgently addressed to facilitate reopening for the 2024/2025 academic year.

Lowmans Leeward Anglican School

The roofs on both buildings are leaking and the spouting needs replacing.

Calder Government School

Immediate loss of electricity, internet and telephone communication. All classrooms and the kitchen floors were flooded. The rain caused all wooden furniture to become waterlogged and a great percentage extensively damaged. Approximately 90% of the roof on the Atlantic side is damaged. All rafters and galvanize on that side would have to be replaced. The casting of the ring beam to secure the roof must be done urgently to avoid further damage.

Kingstown Government School

Damage to the roof on the southern side of the building. Slight damage suffered: A sheet of galvalume from the eastern end of the building was compromised and left flapping. The flapping sheet of galvalume was removed by BRAGSA. Preliminary repairs were done by BRAGSA to avoid further damage to the building contents.

St. Joseph's Convent Kingstown

Roof in the assembly hall, PE room, Pan room, EDPM lab, TVET room have been damaged and partially dislodged.

Lodge Village Government School

Extensive damages were sustained. Roof completely dislodged on half of the old wing. Classrooms exposed to the elements, resulting in damages to equipment and furniture.

Lodge Village Government School

The significant structural damages will adversely impact

Belmont Government School

Urgent repair of the roof and partition are needed in the Grade 2 classroom to prevent further damage.

Paget Farm Government School


The new section of the school has lost most of the roof, resulting in extensive flooding of the classrooms and part of the office. The teacher's bathroom roof is almost completely dislodged. The roof of the old section, that housed the kindergarten, was severely damaged but the metal sheets remain. The support rafters were all ripped out of the wall.

Bishop's College Kingstown

Building sustained extensive roof damages in the following areas: Eight of fourteen classrooms, Staffroom, Library, Science Laboratory, Guidance Counsellor's Office. The areas covering the Information Technology Lab, General Office, and Storeroom are significantly compromised.

Fairhall Primary School

Immediate loss of electricity, internet and communication via telephone.



The boundaries and names shown and the designations used on this map do not imply official endorsement or acceptance by the United Nations or MapAction.

Lower Bay School

The building housing Grades 1, 2, 3 and 4 classes have suffered damage. A third of the roof was dislodged. Several sheets of galvalume from the washroom area were dislodged. A mango tree fell on our backyard garden and may have damaged a newly installed drip irrigation system. The pipe leading from the tank to the garden is broken.

Data Sources

Ministry of Education, St Vincent and the Grenadines Government, OpenStreetMap, GADM, OurAirports, World Port Index.