




# Malawi Flood Event UNDAC Assessments - River Shire East Bank (as of 22 Jan 2015)

The map shows the road conditions on the east bank of the river Shire as assessed by UNDAC teams on 19th January, in the Chikwawa District in South Malawi.

- Legend**
- Displaced People: Camps and Areas
  - City
  - Town
  - Roads
  - M1
  - Rivers
  - District Boundaries
  - Traditional Authority
  - Lakes and Wetlands



**Data sources**  
 Situational: UNDAC  
 Boundaries: GADM  
 Settlements: OSM  
 Transport: OSM  
 Physical features: MASDAP, NASA, OSM

**Created** 22 Jan 2015 / 22:00 UTC+02:00  
**Map Document** MA0015\_Chikwawa\_EastBank\_Road  
**Projection / Datum** WGS 1984 UTM Zone 36S  
**Glide Number** FL-2015-000006-MWI

Produced by MapAction  
[www.mapaction.org](http://www.mapaction.org)  
[malawi@mapaction.org](mailto:malawi@mapaction.org)



The depiction and use of boundaries, names and associated data shown here do not imply endorsement or acceptance by MapAction.

